

	Approved	Equip Profit	Equip #	Item Description	Work Scope	Comments	Driver	Source	STRT Yr(M)	Payoff Yr(M)	Net Yr(M)	Risk Scenario Considered / Analysis	Safety Consequence Likelihood	Health Consequence Likelihood	Environment Consequence Likelihood	Production Consequence Likelihood	PIF	CVE Risk	Compliance Yr(M)	Benefit Cost Ratio	Production Impact Only Yr(M)	Recommended Considerations	Done from comments	Labor	Material	Equipment	Back Page 30%	Contingency 10%	Job Total	Comments	
Item #																															
77	Y	L	0955-367-008	Hot Piping Inspection	C-1100 RD. 4 SIDE C/T OUTLET	hot piping inspection (Dec 15/2021)	AFT Compliance	HRP	H			Not ranked due to AFT Compliance requirement		0	0	0	0	1										\$0	\$0	\$0	0
233	H	L	955-407-000	C1100 01 SC	upgrade pipe to protect against cavitation corrosion	At this time there is not a corrosion issue here's being evaluated. Damaged blackbody	reliability	HRP	H			DERIVED		0	0	0	0	201										\$0	\$0	\$0	0